



CERTIFICATE OF ACCREDITATION

ANSI National Accreditation Board

11617 Coldwater Road, Fort Wayne, IN 46845 USA

This is to certify that

Zero/Six Consulting, LLC

1027 Tremont Street

Galveston, TX 77550

has been assessed by ANAB and meets the requirements of international standard

ISO/IEC 17025:2017

while demonstrating technical competence in the field of

TESTING

Refer to the accompanying Scope of Accreditation for information regarding the types of activities to which this accreditation applies

AT-2090

Certificate Number


ANAB Approval

Certificate Valid Through: 10/26/2020
Version No. 007 Issued: 01/07/2020



This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2017. This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality management system (refer to joint ISO-ILAC-IAF Communiqué dated April 2017).



ANSI National Accreditation Board

SCOPE OF ACCREDITATION TO ISO/IEC 17025:2017

Zero/Six Consulting, LLC

1027 Tremont Street, Galveston, TX 77550

Insert Contacts: William (Bill) H. Coltzer, Jr. Phone: 409 740 0090

Email: bcoltzer@z6consulting.com Website: www.z6cxing.com

TESTING

Valid to: **October 26, 2020**

Certificate Number: **AT-2090**

Construction Materials - Mechanical

Specific Tests and/or Properties Measured	Specification, Standard, Method, or Test Technique	Items, Materials or Product Tested	Key Equipment or Technology
Water infiltration	ASTM E 1105, ASTM E331, ASTM E547, AAMA 501,	Exterior Windows, Doors, Skylights, Curtain Walls	Water Distribution Rack, Centrifugal Blower, Manometer, Wind Generator, Spray Wand
Air Infiltration	ASTM E283, ASTM E783	Exterior Windows, Doors, Skylights, Curtain Walls	Centrifugal Blower, Laminar Flow Element, Manometer
Water and Air Infiltration	AAMA 502, AAMA 503	Exterior Windows, Doors, Skylights, Curtain Walls	Water Distribution Rack, Centrifugal Blower, Manometer
Deflection / Deglazing	ASTM E330, ASTM E987	Exterior Windows, Doors, Skylights, Curtain Walls	Digital Deflection Indicator, Centrifugal Blower
Uplift Force	ASTM E907, FM Global 1-52	Roofing Systems	Uplift Chamber, Manometer, Centrifugal Blower
Forced Entry	ASTM F588, ASTM F842	Windows, Sliding Door Assemblies	Forced Entry Test Kit
Wind/Uplift Resistance	ASTM C1568, ASTM D4541, ASTM E2359/E2359M	Concrete or Clay Tiles,	Construction Load Cell Pull Tester
Roofing, Window Sealant, Foundation Humidity, Cladding Moisture Absorption	ASTM C1521, ASTM D7877, ASTM F2170, Rilem Commission 25/PEM test method 1154)	Miscellaneous	Sealant Test Kit, High & Low Voltage Electronic Detection Units, in situ probes, Rilem Tubes
Whole Building Enclosure Airtightness Compliance	ASTM 779, ASTM 1827, ASTM E1186	Building and Home Enclosures	High Pressure Blower Door Systems, Smoke Tracer Unit, Infrared Camera

Note:

1. The lab for this company is located at 6101 Harborside Dr. Galveston Texas 77552
2. This scope is formatted as part of a single document including Certificate of Accreditation No. AT-2090.



Vice President

