



# CERTIFICATE OF ACCREDITATION

## The ANSI National Accreditation Board

Hereby attests that

**Zero/Six Consulting, LLC**  
**2025 Nichols Ave.**  
**Dickinson, TX 77539**

Fulfills the requirements of

**ISO/IEC 17025:2017**

In the field of

**TESTING**

This certificate is valid only when accompanied by a current scope of accreditation document.  
The current scope of accreditation can be verified at [www.anab.org](http://www.anab.org).

A handwritten signature in black ink, appearing to read 'R. Douglas Leonard Jr.', is positioned above a horizontal line.

R. Douglas Leonard Jr., VP, PILR SBU

Expiry Date: 26 October 2022

Certificate Number: AT-2090



This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2017.  
This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory  
quality management system (refer to joint ISO-ILAC-IAF Communiqué dated April 2017).

## SCOPE OF ACCREDITATION TO ISO/IEC 17025:2017

### Zero/Six Consulting, LLC

2025 Nichols Ave., Dickinson, TX 77539

409 740 0090

William (Bill) H. Coltzer, Jr. [bcoltzer@z6consulting.com](mailto:bcoltzer@z6consulting.com)

Lidija Bikova [LBikova@z6consulting.com](mailto:LBikova@z6consulting.com)

Website: [www.z6consulting.com](http://www.z6consulting.com)

### TESTING

Valid to: **October 26, 2022**

Certificate Number: **AT-2090**

#### Construction Materials - Mechanical

Specific Tests and/or Properties Measured	Specification, Standard, Method, or Test Technique	Items, Materials or Product Tested	Key Equipment or Technology
Water infiltration	ASTM E 1105, ASTM E331, ASTM E547, AAMA 501,	Exterior Windows, Doors, Skylights, Curtain Walls	Water Distribution Rack, Centrifugal Blower, Manometer, Wind Generator, Spray Wand
Air Infiltration	ASTM E283, ASTM E783	Exterior Windows, Doors, Skylights, Curtain Walls	Centrifugal Blower, Laminar Flow Element, Manometer
Water and Air Infiltration	AAMA 502, AAMA 503	Exterior Windows, Doors, Skylights, Curtain Walls	Water Distribution Rack, Centrifugal Blower, Manometer
Deflection / Deglazing	ASTM E330, ASTM E987	Exterior Windows, Doors, Skylights, Curtain Walls	Digital Deflection Indicator, Centrifugal Blower
Uplift Force	ASTM E907, FM Global 1-52	Roofing Systems	Uplift Chamber, Manometer, Centrifugal Blower
Forced Entry	ASTM F588, ASTM F842	Windows, Sliding Door Assemblies	Forced Entry Test Kit
Wind/Uplift Resistance	ASTM C1568, ASTM D4541, ASTM E2359/E2359M	Concrete or Clay Tiles,	Construction Load Cell Pull Tester
Roofing, Window Sealant, Foundation Humidity, Cladding Moisture Absorption	ASTM C1521, ASTM D7877, ASTM F2170, Rilem Commission 25/PEM test method 1154)	Miscellaneous	Sealant Test Kit, High & Low Voltage Electronic Detection Units, in situ probes, Rilem Tubes
Whole Building Enclosure Airtightness Compliance	ASTM 779, ASTM 1827, ASTM E1186	Building and Home Enclosures	High Pressure Blower Door Systems, Smoke Tracer Unit, Infrared Camera

Note:

1. This scope is formatted as part of a single document including Certificate of Accreditation No. AT-2090.
2. The Zero/Six Consulting, LLC office is located at 1027 Tremont Street, Galveston, Texas 77550.



---

R. Douglas Leonard Jr., VP, PILR SBU

